

MAX32660 ERRATA SHEET

Revision A2 Errata

The errata listed below describe situations where components of this revision perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc. may, at its own discretion, take future steps to correct these errata when the opportunity to redesign the product presents itself. Prior to that, Maxim has determined the following potential workarounds that customers may want to consider when addressing one of the situations described below.

This errata sheet only applies to components of this revision. These components are branded on the top side of the package with a six-digit code in the form yywwRR, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively, and RR is the revision of the component. To obtain an errata sheet on other die revisions, visit the Maxim website at www.maximintegrated.com/errata.

1) I2S IN SLAVE MODE CAN RECORD INCORRECT DATA IF A PARTIAL WORD IS RECEIVED DURING LEFT CHANNEL RECEPTION

Description:

While in slave mode, receipt of a partial/truncated word in the left data channel loads incorrect data into the I2S RX_FIFO.

Workaround:

- 1) Do not enable the I2S peripheral while the I2S master is transmitting.
- 2) Ensure that the I2S master begins all transmissions with a complete word.

2) I2S DOES NOT OPERATE AS EXPECTED IF SPIMSSn_DMA.tx_fifo_lvl IS SET TO 0b000

Description:

Transmit data can be corrupted if the I2S transmit FIFO is allowed to empty during a transaction.

Workaround:

The workaround for this erratum is incorporated in the relevant Maxim-supplied API. No user action is required when using the Maxim-supplied API.

In the case the user wants to implement their own API, the workaround is to set the SPIMSSn_DMA.tx_fifo_lvl to a value other than 0b000.

3) I2S PAUSE BIT MUST REMAIN SET A MINIMUM OF TWO LRCLK PERIODS

Description:

Software writes to the SPIMSSn_I2S_CTRL.i2s_pause bit require at least two LRCLK periods to be recognized.

Workaround:

Ensure software delays a minimum of two LRCLK periods between changes to SPIMSSn_I2S_CTRL.i2s_pause.

MAX32660

REV A2 ERRATA

4) SPI MASTER DOES NOT OPERATE AS EXPECTED IF SPI TX_FIFO EMPTY FLAG IS USED

Description:

Transmit data can be corrupted if the TX_FIFO is allowed to empty during a transaction.

Workaround:

The workaround for this erratum is incorporated in the relevant Maxim-supplied API. No user action is required when using the Maxim-supplied API.

In the case the user wants to implement their own API, the workaround is to use the programmable TX_FIFO threshold interrupt instead of the TX_FIFO empty interrupt.

5) DISABLING THE I²C PERIPHERAL DURING A TRANSACTION ERRONEOUSLY SETS THE STOP1 BIT

Description:

Disabling the I²C peripheral during a transaction erroneously sets I2Cn_INTFL0.stopi.

Workaround:

The workaround for this erratum is incorporated in the relevant Maxim-supplied API. No user action is required when using the Maxim-supplied API.

In the case the user wants to implement their own API, the I2Cn_INTFL0.stopi should always be cleared before enabling the I²C peripheral.

6) UART TX_FIFO DOES NOT GENERATE AN INTERRUPT IF EMPTY

Description:

UARTn_CTRL1.tx_fifo_lvlo = 0 does not cause an interrupt when the TX_FIFO becomes empty (ME11-162).

Workaround:

Set UARTn_CTRL1.tx_fifo_lvlo > 0 to cause an interrupt before the TX_FIFO becomes empty.

7) QSPI IN SLAVE MODE DOES NOT OPERATE CORRECTLY, SCK FALL TIME IS SLOW

Description:

SSEL must transition after SCK is already low. This is only an issue in designs with slow falling transitions on SCK (ME11-164).

Workaround:

Ensure the SPI master has sufficient drive capability to pull SCK low before SSEL goes low.

8) UART FIELD UARTn_BAUD1.dbaud MUST BE SET ±3 BITS

Description:

The UART baud rate setting for the IC must differ slightly from the target baud rate (ME11-155).

Workaround:

When calculating the value of UARTn_BAUD1.dbaud, add or subtract 3 bits from the value determined by the formula in the User Guide. The small offset required by this erratum is within the baud rate tolerances of most UART communications.

MAX32660

REV A2 ERRATA

9) RTC_SSEC.ssec IS NOT ACCESSIBLE BY SOFTWARE

Description:

Read operations on the 12-bit RTC_SSEC.ssec field will return an indeterminate value. Write operations on that field will set it to an indeterminate value. The 12-bit subsecond counter itself is not affected and will update the RTC seconds counter RTC_SEC.sec correctly at one second intervals.

Workaround:

None. Do not use the RTC_SSEC.ssec field.

MAX32660

REV A2 ERRATA

Revision History

REVISION NUMBER	REVISION DATE	DESCRIPTION	PAGES CHANGED
0	3/19	Initial release	—
1	3/21	Clarified effect of erratum 9	3

Maxim Integrated cannot assume responsibility for use of any circuitry other than circuitry entirely embodied in a Maxim Integrated product. No circuit patent licenses are implied. Maxim Integrated reserves the right to change the circuitry and specifications without notice at any time.

Maxim Integrated 160 Rio Robles, San Jose, CA 95134 USA 1-408-601-1000

© 2021 Maxim Integrated Products, Inc. Maxim Integrated and the Maxim Integrated logo are trademarks of Maxim Integrated Products, Inc.