

# MAX32590/MAX32591/MAX32592 ERRATA SHEET

## Revision B5 Errata

*The errata listed below describe situations where components of this revision perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc. may, at its own discretion, take future steps to correct these errata when the opportunity to redesign the product presents itself. Prior to that, Maxim has determined the following potential workarounds that customers may want to consider when addressing one of the situations described below.*

*This errata sheet only applies to components of this revision. These components are branded on the topside of the package with a six-digit code in the form yywwRR, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively, and RR is the revision of the component. To obtain an errata sheet on other die revisions, visit the Maxim website at [www.maximintegrated.com/errata](http://www.maximintegrated.com/errata).*

**This errata sheet requires an NDA. To request the full errata sheet, go to [www.maximintegrated.com/MAX32590](http://www.maximintegrated.com/MAX32590) and click on Request Full Data Sheet.**