

MAXQ1850 ERRATA SHEET

Revision B1 Errata

The errata listed below describe situations where MAXQ1850 revision B1 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata when the opportunity to redesign the product presents itself.

This errata sheet only applies to MAXQ1850 revision B1 components. Revision B1 components are branded on the topside of the package with a six-digit code in the form yywwB1, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another MAXQ1850 die revision, visit our website at www.maximintegrated.com/errata.

This errata sheet requires an NDA. For availability, contact the BU at www.maximintegrated.com/MAXQ1850.